## Oil Field Environmental Incident Summary

**Responsible Party:** HUNT OIL COMPANY **Well Operator:** HUNT OIL COMPANY

Well Name: KING 35-4H

Field Name: ROSS Well File #: 17766

Date Incident:10/26/2015Time Incident:16:30Facility ID Number:County:MOUNTRAILTwp: 157Rng: 90Sec: 35Qtr:

Location Description:

Submitted By: Blair Hamilton Received By:

Contact Person: Blair Hamilton

1900 NORTH AKARD STREET DALLAS, TX 75201-2300

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:1 MileDistance Nearest Water Well:1 Mile

Type of Incident: Stuffing Box Leak

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1.5	Barrels	1.5	Barrels	1.5	
Brine	1.5	Barrels	1.5	Barrels	1.5	

Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 11/27/2015 Clean Up Concluded: 10/28/2015

**Risk Evaluation:**None noted.

Areal Extent:

## Potential Environmental Impacts:

None noted.

## Action Taken or Planned:

I shut unit down, tightened stuffing box rubbers and ratigans. Well was left down overnight, until we could establish root cause of problems and test our safety systms. JMAC has been lined up to do a cleanup. We have tested our safety equipment and reviewed safe operating proocedures with operators to minimize recidivism.

Wastes Disposal Location: Indian Hills Disposal, (JMAC) Williston, ND

Agencies Involved:

## **Updates**

Date: 10/27/2015 Status: Reviewed - Assigned to Other Agency Author: Crowdus, Kory

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Release remained on location according to the report. NDIC retains oversight.